

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

**CQ471**  
**NNE**  
**1/2-1**  
**0.737 mi.**  
**3890 ft.**

**CONEY ISLAND YARD**  
**AVENUE X & MACDONALD AVE**  
**BROOKLYN, NY 11233**

**NY Spills** **S109414240**  
**N/A**

**Site 4 of 4 in cluster CQ**

**Relative:**  
**Higher**

**Actual:**  
**13 ft.**

**SPILLS:**

Name: CONEY ISLAND YARD  
Address: AVENUE X & MACDONALD AVE  
City,State,Zip: BROOKLYN, NY 11233  
Spill Number/Closed Date: 0811154 / 2009-01-09  
Facility ID: 0811154  
Facility Type: ER  
DER Facility ID: 357956  
Site ID: 408709  
DEC Region: 2  
Spill Cause: Human Error  
Spill Class: D5  
SWIS: 2401  
Spill Date: 2009-01-08  
Investigator: smsanges  
Referred To: Not reported  
Reported to Dept: 2009-01-08  
CID: Not reported

Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: Not reported  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2009-01-08  
Spill Record Last Update: 2009-01-09  
Spiller Name: SHERRY BULKLAY  
Spiller Company: NYC TRANSIT  
Spiller Address: AVENUE X & MACDONALD AVE  
Spiller Company: 999  
Contact Name: SHERRY BULKLAY  
DEC Memo: "Sangesland reported the Freon release to Randy Austin."  
Remarks: "CALLER STATES THATS A PIPE WAS CUT ON A RAIL CAR RELEASING ABOUT 35 POUNDS OF FREON."

**All Materials:**

Site ID: 408709  
Operable Unit ID: 1165231  
Operable Unit: 01  
Material ID: 2156636  
Material Code: 0050A  
Material Name: freon  
Case No.: Not reported  
Material FA: Other  
Quantity: 35.00  
Units: L  
Recovered: .00  
Oxygenate: Not reported